

# KITCHEN

Kitchen, Chicago, IL July 23, 2009

Report No. 1958

[www.xyzhomeservices.com](http://www.xyzhomeservices.com)

KITCHEN

## Description

**Counter Type:** • Corion/ Corion like

**Range/ Cooktop:** • Electric Ignition

**Hood/ Fan:** • Appears Functional

**Dishwasher:** • Appears Functional

## Limitations

**Garbage disposal:** • Dishes block full view of disposals

**Plumbing:** • View below sink(s) restricted by supplies, etc.

## Recommendations

### Counters/ Cabinets \ Counters

**Condition:** • Missing/ Caulking in places

**Task:** Correct

**Time:** Regular maintenance

**Cost:** Minor

### Range/ Cooktop \ Exhaust

**Condition:** • Vent filter soiled/ missing/ damaged

**Task:** Replace

**Time:** Regular maintenance

### Dishwasher \ General

**Condition:** • Unit makes unusual noise

**Location:** Kitchen

**Task:** Further evaluation

**Cost:** Depends on work needed

**END OF REPORT**