

# PARKING

76 Woolwich, Chicago, IL July 29, 2009

Report No. 1955

[www.xyzhomeservices.com](http://www.xyzhomeservices.com)

## PARKING

### Description

**Parking Structure Type:** • Garage - attached  
**Number of cars:** • 1  
**Floor and floor type:** • Concrete slab  
**Garage Doors:** • Metal  
**Automatic openers:** • Appears functional  
**Exterior side door:** • Solid core  
**Roof:** • Asphalt shingle, plywood sheathing, rafters

### Limitations

**Roof:** • Access limited due to steepness/ height  
**Interior:**  
• % obscured by storage/ wallcoverings  
*Note: 85*  
**Automatic Openers:** • Remote control devices not tested

### Recommendations

#### Exterior \ Vents

**Condition:** • Vent(s) blocked  
**Location:** West Exterior Wall  
**Task:** Correct  
**Time:** Immediate

#### Floor \ Floor finish

**Condition:** • Oil stains noted  
**Location:** Center  
**Task:** Clean  
**Time:** Regular maintenance

#### Exterior side door \ General

**Condition:** • Moderate/ Major delamination  
**Task:** Replace  
**Time:** Discretionary

**END OF REPORT**