

POOL&SPA

Pool and Spa report, Chicago, IL July 23, 2009

Report No. 1957

www.xyzhomeservices.com

POOL&SPA

Description

Liner: • Vinyl

Coping: • Tile

Deck: • Concrete

Accessories: • Diving board • Ladder • Heater

Limitations

Heater: • Not tested

Recommendations

Pool and Water \ Liner

Condition: • Pitted

Location: East

Task: Monitor

Coping and Deck \ Deck

Condition: • Surface slippery

Location: Throughout

Task: Correct

Time: Immediate

Note: Smooth surfaces are a safety hazard.

END OF REPORT