

POOL&SPA

WOOD DEST

RADON

Description

Liner: • Vinyl

Coping: • Tile

Deck: • Concrete

Accessories: • Diving board • Ladder • Heater

Limitations

Heater: • Not tested

Recommendations

Pool and Water \ Liner

Condition: • Pitted

Location: East

Task: Monitor

Coping and Deck \ Deck

Condition: • Surface slippery

Location: Throughout

Task: Correct

Time: Immediate

Note: Smooth surfaces are a safety hazard.

WOOD DESTROYING INSECTS

Pool and Spa report, Chicago, IL July 23, 2009

Report No. 1957

www.xyzhomeservices.com

POOL&SPA

WOOD DEST

RADON

Description

Visible Evidence of Active Wood Destroying Insects: • NO

Limitations

Areas Excluded from Report: • Inaccessible areas of substructural crawl space

RADON

Pool and Spa report, Chicago, IL July 23, 2009

Report No. 1957

www.xyzhomeservices.com

POOL&SPA

WOOD DEST

RADON

Description

Monitor Placement: • Basement

Measurement Period:

• Start Time:

Note: July 23, 2009

• End Time:

Note: July 26, 2009

• 48 hour

Type: • LSC (Liquid Scintillation counter)

Calibration Date:: • July 20, 2009

Result: • EPA RECOMMENDS: FIX YOUR HOME IF YOUR RADON LEVEL IS 4 PICOCURIES PER LITER (pCi/L) OR HIGHER.

Result:

• Your average test result is:

Note: 3.3 pCi/l

Representative:

• Placed by:

Note: John Kwasnik

• Retrieved by:

Note: John Kwasnik

END OF REPORT